




Thomas C Thompson 09/516,655 Rafter Tie Plat Sheathing Tie



not accepted
e.l. 10/5/05

FIG. I



Th omas C Thompson 09/516,655 Rafter Top Plate Sheathing Tie




FIG. 2

*Not accepted
E-L, 10/5/05*



Th mas C Th mpson 09/516,655 Rafter Tie Plate Sheathing Tie





FIG. 3

not accepted
Ed., 10/15/05




Th mas C Th mpson 09/516,655 Rafter Top Plate Sheathing Tie



not accepted
GL, 10/5/05

FIG. 4



Thomas C Thompson 09/516,655 Rafter Top Plate Sheathing Tie





FIG. 5

not accepted
g-l. 10/5/05



Th mas C Thompson 09/516,655 Rafter Top Plate Sheathing TI




FIG. 6

not accepted
10/5/05
g.f.